Territooriumi skeem / Site Layout / План территории



Promens Rõngu AS

1. Väravavalve / Gate Security
2. Veokite parkla / Truck parking
3. Kauba väljastamine /Goods out
4. Ladu / Warehouse
5. Ladu / Warehouse
6. Kauba vastuvõtt / Receipt of goods
7. Ladu / Warehouse
8. Tootmine / Production
9. Külaliste parkla / Guests parking
10. Kontor / Office
11. Sepikoda / Workshop
12. Pumpla /Pump station



The speed limit for vehicles on the external premises of Promens Rõngu AS is 10 km/h.

Smoking, including e -cigarettes , is allowed only in designated areas .

Photography and filming are not allowed without permission. Please ask for approval from your host or the factory representative.

It is prohibited to bring alcohol and other narcotic substances to the territory of Promens Rõngu AS and to enter the territory in a state of intoxication.

Without a permit, it is not allowed to bring hazardous chemicals into the territory of Promens Rõngu AS. If necessary, ask permission from the person you are visiting.

PROMENS RÕNGU AS

SAFETY AND INFORMATION FOR GUESTS

Tehase 4, 61001 Rõngu, Eesti

+372 730 7230

info.rongu@sapagroup.it

READ
carefully the instructions and ask for information if necessary

Conduct in the event of a fire and evacuation



In case of fire, proceed to the assembly point located in front of the office building along the pedestrian walkway.



Follow the green evacuation signs and stay close to the person you are visiting.



Evacuation staff will wear a red vest during the evacuation. They can help you if you need help finding a safe exit to the assembly point.

Production area 6 000 m²
Warehouse area 11 000 m²
Approximately 200 employees
Revenue approximately €23 M
Recycled polymer 2700 tons

Personal protective equipment for visitors



Wearing safety footwear is mandatory in all production and warehouse areas.



Wearing a reflective vest for guests is mandatory in all production and storage areas.



Wearing hearing protectors is mandatory in certain production areas, and the use of hearing protectors is recommended in the main production rooms.



Watch out for the signs! In certain areas and when performing specific work operations, the use of additional personal protective equipment (PPE) may also be necessary. Consult your host or the factory representative.

Traffic on the territory

In order to avoid health damage and accidents, everyone on the territory of Promens Rõngu AS must be aware of the main risks of the working environment:



Risk of slipping and falling. Sources of danger include winter ice, fallen plastic pellets and wet floors. Be careful!



Intensive vehicle traffic (car, trucks, forklifts, stackers. Be attentive!



High shelves for mould and material. Objects falling from heights can cause severe trauma. Keep a safe distance!



Dangerous machinery and equipment. Avoid contact with them, do not cross protective barriers that prevent access to danger areas.



It is STRICTLY FORBIDDEN to be in the danger zone of the lifting area or to pass under the hanging cargo while the injection molds are being moved. The marking of the danger area of lifting areas is created on the floor with a red light. punase valgusega.